

	Type	Hits	Search Text
1	BRS	591	"friction wedge"
2	BRS	59	"friction wedge" same trucks
3	BRS	367	friction same wedge same trucks
4	BRS	0	friction same wedge same trucks same matrix
5	BRS	19	friction same wedge same trucks same liner
6	BRS	265	"31008"
7	BRS	0	"Re 31008"
8	BRS	2	"Re31008"
9	BRS	54	COnnel.inv.
10	BRS	188	"31988"

	DBs	Time Stamp	Comments	Error Definition	Error	Ref #
1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:18				S1
2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 09:45				S2
3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:18				S3
4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 09:45				S4
5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 09:58				S5
6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:03				S6
7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 09:59				S7
8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:00				S8
9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:02				S9
10	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:03				S10

	Type	Hits	Search Text
11	BRS	0	"31988" and Lighthall
12	BRS	0	"31008" and Connel
13	BRS	0	"RE 34903"
14	BRS	2	"RE34903"
15	BRS	2	"Re34903"
16	BRS	0	"friction wedge" same composite same liner
17	BRS	357	friction same wedge same liner
18	BRS	9	friction same wedge same liner same composite
19	BRS	84	composite same liner same wedge
20	BRS	9	composite same liner same friction same wedge

	DBs	Time Stamp	Comments	Error Definition	Errors	Ref #
11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:03				S11
12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:03				S12
13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:04				S13
14	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:06				S14
15	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:06				S16
16	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:18				S25
17	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:18				S26
18	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:28				S27
19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:30				S29
20	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:32				S30

	Type	Hits	Search Text
21	BRS	2	"4167907".pn.
22	BRS	8365	friction same damper
23	BRS	159	friction same damper same wedge
24	BRS	6	friction same damper same composite same wedge
25	BRS	161	friction same damper same composite
26	BRS	4	"4230047".pn.
27	BRS	3	"4244298".pn.
28	BRS	2	"4254713".pn.
29	BRS	2	"6701850".pn.
30	BRS	452	105/198.2

	DBs	Time Stamp	Comments	Error Definition	Errors	Ref #
21	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:37				S33
22	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:37				S34
23	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:37				S35
24	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:38				S37
25	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:45				S36
26	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:46				S38
27	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 16:10				S39
28	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 10:48				S40
29	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 11:50				S73
30	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 11:50				S75

	Type	Hits	Search Text
31	BRS	104	105/198.3
32	BRS	234	105/198.5
33	IS&R	797	(105/198.2,198.3,198.4) .CCLS.
34	BRS	653	105/207

	DBs	Time Stamp	Comments	Error Definition	Errors	Ref #
31	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 12:02				S76
32	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 11:53				S74
33	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 12:02				S78
34	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2004/12/02 12:43				S79